

Inspection Photos
Operator: Simcoe
API: 067-08875
Date: 12/23/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Perennial vegetation such as intermediate wheatgrass is observable. Final reclamation will require revegetation with vegetation representative of the reference area.



Photo 3. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, sand dropseed, blue grama, and James galleta.



Photo 4. View of closed gate after leaving location