

Inspection Photos

Loc#427776

Operator: Grizzly

Insp #: 692402784

Insp Date: 12/17/2020





Photo#1:
Overview of Location to Northwest.

December 17,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly MDP Loc#427776



Photo#2:
BMPs .



Photo#3:
BMPs.

December 17,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly MDP Loc#427776



Photo#4:
BMPs



Photo#5:
BMPs.

December 17,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly MDP Loc#427776