

Inspection Photos
Location Name: Powers 11-27
Location ID: 332396



Photo 1 leaking valve in meter house has been repaired

Photo 2 stained concrete in meter house has been cleaned

Inspection Photos
Location Name: Powers 11-27
Location ID: 332396



Photo 3 stained soil under valve on crude oi tank has been cleaned