

Inspection Photos
Location Name: Arends X21-9
Location ID: 310107



Photo 1 WH sign




Photo 2 WH

Inspection Photos
Location Name: Arends X21-9
Location ID: 310107



Photo 3 TB sign



Photo 4 TB



Inspection Photos

Location Name: Arends X21-9
Location ID: 310107



Photo 5 Gas Meter Run




Photo 6 Card in meter house

Inspection Photos
Location Name: Arends X21-9
Location ID: 310107



Photo 7 ECd



Photo 8 Horizontal Heated Separator