

Inspection Photos

API: 009-06600

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 12/29/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 12/29/2020

Inspection Photos




Photo 1. Facing west toward the location. It appears additional reclamation has recently been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 12/29/2020

Inspection Photos



Photo 2. Facing east at the location. It appears additional reclamation has recently been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 12/29/2020

Inspection Photos



Photo 3. Facing west toward the surrounding undisturbed pasture which consists of a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06600 | Date: 12/29/2020