

Inspection Photos

API: 009-06158

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020

Inspection Photos




Photo 1. Facing west toward the location. There are areas at the location that have no vegetation growth. Areas bare of vegetation need to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020

Inspection Photos




Photo 2. Facing southeast at the location. There are areas at the location that have no vegetation growth. Areas bare of vegetation need to be reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020

Inspection Photos



Photo 3. View of groundcover showing no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020

Inspection Photos



Photo 4. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020

Inspection Photos



Photo 5. Facing west toward the surrounding undisturbed pasture which consists of a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06158 | Date: 12/29/2020