



40.08338, -108.72364, 5444.1ft, 138°
12/28/2020 08:10:37 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781



40.08334, -108.72358, 5453.2ft, 41°
12/28/2020 08:11:01 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well

gas venting

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781



40.08333, -108.72356, 5459.8ft, 344°
12/28/2020 08:14:41 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well gas venting

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781



40.08333, -108.72356, 5459.7ft, 27°
12/28/2020 08:15:10 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well gas venting

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781



40.08294, -108.72341, 5452.7ft, 162°
12/28/2020 08:25:51 AM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank.

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tank.

Little Gilliam 1

API: 05-103-07380

Inspection: 700404781