



40.07196, -108.7713, 5239.4ft, 49°
12/28/2020 09:04:19 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack.

Tranco 5A API: 05-103-05320
Inspection: 700404785



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.


Tranco 5A API: 05-103-05320
Inspection: 700404785



40.07194, -108.77126, 5238.6ft, 52°
12/28/2020 09:08:23 AM



40.071, -108.77317, 5267.3ft, 129°
12/28/2020 08:57:31 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Lower part of north tank.

Tranco 5A API: 05-103-05320
Inspection: 700404785