

Final Reclamation Inspection

December 31, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335772

Inspection Document #: 697502369

Weld County, CO

NESW Section 25 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAM-61N66W 25NESW
Location ID: 335772



Photo 1. Photo taken from the western location, facing East. Photo illustrates Operator has removed all equipment from location. It appears public disturbances (trucks and ATV's) are tearing up the location. Operator has put up barriers to exclude public access; however, that is not working.

Inspection Photos
Location Name: SAM-61N66W 25NESW
Location ID: 335772



Photo 2. Photo taken from the northern location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: SAM-61N66W 25NESW
Location ID: 335772



Photo 3. Photo taken from the northern location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: SAM-61N66W 25NESW
Location ID: 335772



Photo 4. Photo taken from the central location, facing Southwest. Photo illustrates where the public is entering into the location.

Inspection Photos
Location Name: SAM-61N66W 25NESW
Location ID: 335772



Photo 5. Photo taken from the central location, facing West. Photo illustrates the barriers the Operator has implemented.