

# Final Reclamation Inspection

December 31, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 319592

Inspection Document #: 697502371

Weld County, CO

NESE Section 25 T1N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: WENZEL #1  
Location ID: 319592



**Photo 1.** Google Earth aerial from 6/9/2017 illustrating active operations.

Inspection Photos  
Location Name: WENZEL #1  
Location ID: 319592



**Photo 2.** Google Earth aerial from 9/12/2019 illustrating conditions after plugging and abandonment. Photo illustrates the Operator has failed to reclaim the access road.



Inspection Photos  
Location Name: WENZEL #1  
Location ID: 319592



**Photo 3.** Photo taken from the western access road, facing West. Photo illustrates unmanaged weeds along the access road. Gravel remains along the access road and has not been returned back to cropland.



Inspection Photos  
Location Name: WENZEL #1  
Location ID: 319592



**Photo 4.** Photo taken from the western access road, facing East. See comments under Photo 3.