

Interim Reclamation and Stormwater Inspection

December 31, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 453474

Inspection Document #: 697502373

Weld County, CO

NWSW Section 25 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 1. Photo taken from the southern well location, facing North. Photo illustrates Operator is in-process of performing interim reclamation activities.



Photo 2. Photo taken from the southern well location, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 3. Photo taken from the southern well location, facing Northeast. See comments under Photo 1.



Photo 4. Photo taken from the southern well location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 5. Photo taken from the southeastern well location, facing Northeast. See comments under Photo 1.



Photo 6. Photo taken from the southeastern well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 7. Photo taken from the southern facility location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 8. Photo taken from the southern access road, facing North. Photo illustrates the access road is in good condition.



Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 9. Photo taken from the southern access road, facing South. Photo illustrates the VTC device is in need of maintenance. At the time of this inspection, there was no observed track out onto the public road.

