

Final Reclamation Inspection

December 31, 2020

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 453474

Inspection Document #: 697502375

Weld County, CO

NWSW Section 25 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Sam /25H-M166
Location ID: 453474



Photo 1. Photo taken from the location, facing Northwest. Photo illustrates only eleven, 11, wells have been drilled at location; therefore, this is a well release on an active location.

