

# Inspection Photos

API: 009-05055

Operator: COLORADO INTERSTATE GAS  
COMPANY LLC

Inspection Date: 12/29/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05055 | Date: 12/29/2020

## Inspection Photos



**Photo 1.** Facing southwest toward the location. Well has been plugged and abandoned. All equipment has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05055 | Date: 12/29/2020

## Inspection Photos



**Photo 2.** Facing northeast toward the location. Vegetation has not fully established in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05055 | Date: 12/29/2020

## Inspection Photos



**Photo 3.** Facing northwest toward the location. Vegetation has not fully established in areas of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05055 | Date: 12/29/2020

## Inspection Photos



**Photo 4.** View of ground cover which shows areas with no vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-05055 | Date: 12/29/2020