

Inspection Photos

API: 009-05080

Operator: COLORADO INTERSTATE GAS
COMPANY LLC

Inspection Date: 12/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 1. Facing west toward the access road. The cattle guard has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 3. There is pipe risers and equipment that remain at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 4. Facing north toward the location. There is no vegetation in areas of the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 5. View of ground cover at the location shows no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed reference area which consists of a uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05080 | Date: 12/29/2020