

Bradenhead Pressure Action Threshold 605 psig

This threshold is calculated per Rule 308A.b.(2)G. If this well is located in a bradenhead test area (see Rule 207.b) per an Order of the Commission, it may be subject to a different threshold.

Does the casing centralization comply with Rule 317.g? Yes

If "NO", provide details below.

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

| Method used | String | Cementing tool setting/perf depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| | | | | | |

Details of work:

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analysis must be submitted to COGCC) |
|----------------|----------------|--------|------------------|-------|---|
| | Top | Bottom | DST | Cored | |
| | | | | | |

Operator Comments:

This well was drilled during the second rig occupation on the Tower LD Pad.

Surface was set on the Tower LD 19-219HN on 11/7/2020. Activities were suspended on 11/7/2020, prior to reaching TD due to changing rig priorities. Great Western anticipates recommencing drilling in Q1 of 2022 with a large rig and plans to set production casing prior to completing the well in Q2 of 2022.

The TPZ and BHL footages are taken from the APD.

The depths are from the smaller surface rig and will change based on the production rig's KB on the final reports.

No logs were run on this well.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Eileen Roberts

Title: Regulatory Analyst

Date: _____

Email: eroberts@gwp.com

Attachment Check List

| Att Doc Num | Document Name | attached ? | |
|-----------------------------|-----------------------|---|--|
| <u>Attachment Checklist</u> | | | |
| 402563107 | CMT Summary * | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | Core Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| 402558195 | Directional Survey ** | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |
| | DST Analysis | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Logs | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| | Other | Yes <input type="checkbox"/> | No <input checked="" type="checkbox"/> |
| <u>Other Attachments</u> | | | |
| 402558197 | DIRECTIONAL DATA | Yes <input checked="" type="checkbox"/> | No <input type="checkbox"/> |

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | Stamp Upon Approval |

Total: 0 comment(s)

