

Final Reclamation Inspection

December 31, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 424877

Inspection Document #: 697502385

Weld County, CO

NWSW Section 27 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates Operator has responded to the previous corrective action to manage and control all noxious weeds. Photo illustrates Operator has put in an additional section of fence and has performed additional reclamation activities with the evidence of straw crimped mulch.



Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 2. Photo taken from the entrance of location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 3. Photo taken from the entrance of location, facing North. See comments under Photo 1.

