

Final Reclamation Inspection

December 31, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 424495

Inspection Document #: 697502387

Weld County, CO

NWNW Section 27 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RITCHEY USX # WW27-04
Location ID: 424495



Photo 1. Photo taken from the southern tank battery location, facing South. Photo illustrates Operator has responded to the previous corrective action to manage and control all noxious weeds and has removed all equipment. Operator has also performed final reclamation activities with the evidence of straw crimped mulch.



Inspection Photos
Location Name: RITCHEY USX # WW27-04
Location ID: 424495



Photo 2. Photo taken from the entrance of location, facing South. See comments under Photo 1.

