



40.09307, -108.84209, 5221.4ft, 251°
12/28/2020 12:34:38 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack.

A.C. McLaughlin 61

API: 05-103-05467

Inspection: 700404808



40.09304, -108.84218, 5216.2ft, 14°
12/28/2020 12:34:57 PM



40.09306, -108.84217, 5218.2ft, 13°
12/28/2020 12:38:26 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well gas venting.

A.C. McLaughlin 61

API: 05-103-05467

Inspection: 700404808



40.09309, -108.84197, 5216.1ft, 56°
12/28/2020 12:34:17 PM