



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Pump jack.


Gebauer 14

API: 05-103-07049

Inspection: 700404828



40.06807, -108.80275, 5343.1ft, 315°
12/28/2020 03:36:23 PM



40.0681, -108.80276, 5344.3ft, 350°
12/28/2020 03:36:36 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well.

Gas venting.

Gebauer 14

API: 05-103-07049

Inspection: 700404828





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Pit & tank.

Gebauer 14

API: 05-103-07049

Inspection: 700404828