

# Inspection Photos

API: 009-06573

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 12/29/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020

## Inspection Photos



**Photo 1.** Facing northwest along the access road. Areas along the road have no vegetation establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020

## Inspection Photos



**Photo 2.** Facing east toward the location. All equipment has been removed from the location. Vegetation does not appear to be establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020

## Inspection Photos



**Photo 3.** Facing east toward the location. All equipment has been removed from the location. Vegetation does not appear to be establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020

## Inspection Photos



**Photo 4.** View of ground cover at the location shows no vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020

## Inspection Photos



**Photo 5.** Facing west toward the surrounding undisturbed pasture which consists of a uniform vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06573 | Date: 12/29/2020