

Inspection Photos

Loc#323973

Operator: Terra

Insp#: 692402810

Insp Date: 12/22/20





Photo#1:
Overview of Location from Entry.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Savage Loc#323973



Photo#2:
BMP.



Photo#3:
Interim area.

December 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Savage loc#323973