

# *Inspection Photos*

*Loc#335487*

*Operator: Terra*

*Inspection Number: 692402812*

*Inspection Date: 12/22/20*





Photo#1:  
Overview of Location from Entry.

December 22, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Potter loc#335487



Photo#2:  
Pad area.



Photo#3:  
Interim area.

December 22, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Potter loc#335487



Photo#4:  
Fencing Repaired.



Photo#5:  
Russian Olive.

December 22, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Potter loc#335487