

# *Inspection Photos*

*Loc#324097*

*Operator: Terra*

*Insp#: 692402813*

*Insp Date: 12/22/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry.

December 22, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Savage 324097



Photo#2:  
Debris cleaned from equipment area.



Photo#3:  
Debris cleaned from equipment area

December 22, 2020





Photo#2:  
Well positioned in irrigated field.



Photo#3:  
Track leading from Well to equipment location.

December 22, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Savage 324097