

Inspection Photos
Location Name: Leffler 26-A Pad
Location ID: 433335



Photo 1: Wellheads



Photo 2: Wellheads

Inspection Photos
Location Name: Leffler 26-A Pad
Location ID: 433335



Photo 3: Tank Battery



Photo 4: Unused equipment

Inspection Photos
Location Name: Leffler 26-A Pad
Location ID: 433335



Photo 5: Unused equipment



Photo 6: No visible labeling