

Inspection Photos
Location Name: Pronghorn T-P-3HNB
Location ID: 431184



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Pronghorn T-P-3HNB
Location ID: 431184



Photo 3 – Gas Meter, ECDs



Photo 4 – Separators



Inspection Photos
Location Name: Pronghorn T-P-3HNB
Location ID: 431184



Photo 5 – Compressor



Photo 6 – Pumping Unit

Inspection Photos
Location Name: Pronghorn T-P-3HNB
Location ID: 431184



Photo 7 – Pumping Unit



Photo 8 – Gas Lift Meter



Inspection Photos
Location Name: Pronghorn T-P-3HNB
Location ID: 431184



Photo 9 – Stained Soil at Compressor



Photo 10 – Unmarked 1" Riser at North end of Rack

