

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2020

Submitted Date:

12/30/2020

Document Number:

679603584**FIELD INSPECTION FORM**
 Loc ID 451277 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**26 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451510	WELL	PR	09/05/2018	OW	123-45101	Falken 33N-9B-L	PR
451514	WELL	PR	09/24/2018	OW	123-45103	Falken 32N-9B-L	PR
451515	WELL	PR	09/05/2018	OW	123-45104	Falken 4N-14A-S	PR
451518	WELL	PR	09/22/2018	OW	123-45106	Falken State 34N-9C-L	PR
451519	WELL	PR	09/05/2018	OW	123-45107	Falken 33N-9A-L	PR
451530	WELL	PR	09/08/2018	OW	123-45111	Falken 30N-14B-S	PR
451532	WELL	PR	09/05/2018	OW	123-45112	Falken 33C-9-L	PR
451535	WELL	PR	09/05/2018	OW	123-45114	Falken 33N-9C-L	PR
451536	WELL	PR	09/27/2018	OW	123-45115	Falken 32C-9-L	PR
451537	WELL	PR	09/26/2018	OW	123-45116	Falken 31C-14-S	PR
451539	WELL	PR	09/22/2018	OW	123-45117	Falken 9C-9-L	PR
451542	WELL	PR	09/07/2018	OW	123-45119	Falken 30C-14-S	PR
451544	WELL	PR	09/22/2018	OW	123-45120	Falken 16N-9B-L	PR
451546	WELL	PR	09/05/2018	OW	123-45121	Falken 31N-14B-S	PR
451547	WELL	PR	09/25/2018	OW	123-45122	Falken 9N-9C-L	PR
451551	WELL	PR	09/05/2018	OW	123-45124	Falken 4N-14C-S	PR
451552	WELL	PR	09/24/2018	OW	123-45125	Falken State 34C-9-L	PR
451555	WELL	PR	09/23/2018	OW	123-45127	Falken 16C-9-L	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	one tank does not have labeling. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	03/30/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	iron		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 18		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 18		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		

Comment:		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 5		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	23 TOTAL	Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 18		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV CONCRETE		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	UNKNOWN
Other (Capacity)	UNKNOWN
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	8	400 BBLs	STEEL AST		40.502500,-104.735800	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	451510	Type:	WELL	API Number:	123-45101	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	pr								
Corrective Action:						Date:			
Facility ID:	451514	Type:	WELL	API Number:	123-45103	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451515	Type:	WELL	API Number:	123-45104	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451518	Type:	WELL	API Number:	123-45106	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451519	Type:	WELL	API Number:	123-45107	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451530	Type:	WELL	API Number:	123-45111	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451532	Type:	WELL	API Number:	123-45112	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451535	Type:	WELL	API Number:	123-45114	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	451536	Type:	WELL	API Number:	123-45115	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451537	Type:	WELL	API Number:	123-45116	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451539	Type:	WELL	API Number:	123-45117	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451542	Type:	WELL	API Number:	123-45119	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451544	Type:	WELL	API Number:	123-45120	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451546	Type:	WELL	API Number:	123-45121	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451547	Type:	WELL	API Number:	123-45122	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451551	Type:	WELL	API Number:	123-45124	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			

Facility ID:	451552	Type:	WELL	API Number:	123-45125	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

Facility ID:	451555	Type:	WELL	API Number:	123-45127	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b></p> <p><b>**Weather Conditions:</b> snow on ground, sunny</p> <p>On Wednesday, December 30, 2020 at approximately 13:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at FALKEN 9-11 PAD (PDC Energy), at location #: 451277 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. One tank does not contain any labeling. Install sign to comply with Rule 210.d.</p> <p>(Corrective Action Date: March 30, 2020) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	12/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603585	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321385">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5321385</a>