

Inspection Photos
Location Name: Pronghorn F-10 PAD
Location ID: 431387



Photo 1 – Separators



Photo 2 – Tank Battery

Inspection Photos
Location Name: Pronghorn F-10 PAD
Location ID: 431387




Photo 3 – Wells



Photo 4 - Wells

Inspection Photos
Location Name: Pronghorn F-10 PAD
Location ID: 431387




Photo 5 – K-O-10 Wellhead Sign missing



Photo 6 – Risers have been marked

Inspection Photos
Location Name: Pronghorn F-10 PAD
Location ID: 431387



Photo 7 – Risers have been marked