

Inspection Photos  
Operator: Simcoe  
API: 067-07851  
Date: 1/4/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Perennial vegetation such as western wheatgrass and rubber rabbitbrush observed above the snow.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of dense Scotch thistles observed along the access road. Approximately 150 individuals observed.



Photo 5. View of closed gate after leaving location