

Inspection Photos
Operator: Simcoe
API: 067-09600
Date: 1/4/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Location largely snow covered at this time.



Photo 3. View of equipment stored within the project area.



Photo 4. View of musk thistles observed along the access road.



Photo 5. View of reference area comprised of irrigated grass field, largely snow covered.



Photo 6. View of closed gate after leaving location