

Inspection Photos
Operator: Simcoe
API: 067-07705
Date: 1/4/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses observed such as smooth brome, thickspike wheatgrass, and sideoats grama.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of Canada thistles observed within the northern project area. Approximately 100 dormant individuals observed.



Photo 5. View of reference area comprised of open grass field with grasses such as smooth brome, western wheatgrass, and thickspike wheatgrass.



Photo 6. View of closed gate after leaving location