

Final Reclamation Inspection

January 5, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 422552

Inspection Document #: 697502389

Weld County, CO

SENE Section 23 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the access road which has not been reclaimed per Rule 1004.

Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 2. Photo taken from the northern access road, facing West. Photo illustrates the Operator has failed to remove gravel and perform final reclamation activities.

Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 3. Close up photo taken from the northern access road. Photo illustrates the Operator has failed to remove gravel and perform final reclamation activities.



Photo 4. Close up reference photo taken west of the access road, illustrating the failure to remove gravel and perform final reclamation activities.



Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 5. Photo taken from a portion of the access road, facing South. See comments under Photo 1 and 2.



Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 6. Photo taken from the DA location, facing South. Photo illustrates a mound of gravel which has not been removed and reclaimed.



Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 7. Reference photo taken east of the DA location, facing East. Photo illustrates the reference vegetation is mostly comprised of blue grama with some western wheatgrass, sand dropseed, and purple three-awn.

