

Final Reclamation Inspection

January 5, 2021

Operator: WESTERN OPERATING COMPANY - 95620

API #: 05-123-05490

Inspection Document #: 697502391

Weld County, CO

SESE Section 27 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SPEAKER #P
API #: 05-123-05490



Photo 1. Photo taken from the well location, facing North. Photo illustrates the Operator has failed to remove all equipment per Rule 1004.

