




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Dragon Trail Unit 1301      API: 05-103-05153**  
**Inspection: 700404859**



39.86434, -108.89419, 6345.5ft, 333°  
01/05/2021 12:33:05 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**Dragon Trail Unit 1301**

**API: 05-103-05153**

**Inspection: 700404859**





39.86435, -108.89417, 6303.1ft, 342°  
01/05/2021 12:45:25 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Wheel valve at well.**

**Gas leak.**

**Dragon Trail Unit 1301**

**API: 05-103-05153**

**Inspection: 700404859**