

Inspection Photos
Location Name: Markham 15-11 I 8
Location ID: 329818



Production facility



Wellhead



Inspection Photos
Location Name: Markham 15-11 I 8
Location ID: 329818

dcp
Midstream.

STATION NO. 213219

STATION NAME Markham 15-11

STATIC RANGE 500 DIFF. RANGE 250

TEMPERATURE RANGE 200

METER RUN SIZE 3.067

| DATE | ORIFICE SIZE | TEST DATE |
|------|--------------|----------------|
| | <u>1.250</u> | <u>2-15-08</u> |
| | <u>1.250</u> | <u>8-21-08</u> |
| | <u>1.250</u> | <u>2-25-08</u> |
| | <u>1.250</u> | <u>8-21-09</u> |
| | | |
| | | |
| | | |
| | | |

Colorado Oil & Gas Conservation Commission
40.31018, -104.99341, 1482.6m, 12°
10/28/2020 09:32:01

Calibration card on 10/28/2020

dcp
Midstream.

STATION NO. 213219

STATION NAME Markham 15-11

STATIC RANGE 500 DIFF. RANGE 250

TEMPERATURE RANGE 200

METER RUN SIZE 3.067

| DATE | ORIFICE SIZE | TEST DATE |
|------|--------------|----------------|
| | <u>1.250</u> | <u>2-15-08</u> |
| | <u>1.250</u> | <u>8-21-08</u> |
| | <u>1.250</u> | <u>2-25-08</u> |
| | <u>1.250</u> | <u>8-21-09</u> |
| | <u>1.250</u> | <u>1-4-21</u> |
| | | |
| | | |
| | | |

Colorado Oil & Gas Conservation Commission
40.31016, -104.99337, 1484.4m, 308°
01/06/2021 11:21:14

Calibration card on 1/6/2021