

# Inspection Photos

1/04/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo shows active wells on Location.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171




**Photo 2:** Photo taken from the north end of the Location, facing west. Photo shows anchor markers observed on Location.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171



**Photo 3:** Photo taken from the northern area of the Location, facing northeast. Photo shows separator and tank equipment on the Location.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



**Photo 4:** Photo taken from the north end of the Location, facing northeast. Photo shows cut slope. Erosion degradation and stability concerns observed. BMPs to stabilize/protect slopes missing or insufficient.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



**Photo 5:** Photo taken from the north end of the Location, facing northwest. See comments under photo 4.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



**Photo 6:** Photo taken from the north end of the Location, facing north. See comments under photo 4.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171



**Photo 7:** Photo taken from the northeast end of the Location, facing west. See comments under photo 4





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171



**Photo 8:** Photo taken from the east end of the Location facing southwest. Photos 8-9 provide an overview of the Location from southwest to northwest.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335171



**Photo 9:** See comments under photo 8.

