

Inspected Facilities

Facility ID: 260968 Type: WELL API Number: 071-07484 Status: PR Insp. Status: PR

Complaint

Comment:

Field Inspector Assigned: Tom E. Beardslee

Complaint Received:

Date: 12/3/2020

Complaint Contacted:

Date: 12/3/2020 Time 11:30 Hrs

Location #: 260968 & 287124

Inspection Document #: 695103720, 695103721

Nature of complaint: Noise/road conditions.

Field Inspector Actions:

On 12-03-2020, I was contacted by my supervisor Steve Labowskie in reference to a complaint received by the COGCC in reference to noise and road conditions. The complaint states that Noise from the Hill 33-22 Well, the Centerfire 42-22 well the Cottontail Compressor station is very loud, at times they can be heard inside of complainants cabin. Noise typically occurs Mornings and night. Sometimes all day, wind dependent with complainant's location; at the sites, the noise is continuous all day. Noise was described as noise you hear and feel. The complaint also states that the roads within Whispering Pines Estates, un named, 43.5, 30.1. The Roads are not kept up to the standards of the Road Use Agreement that was put in place upon the start of the gas wells and road construction.

On 12-03-2020 at 11:30, I attempted to make contact with the complaint on his home phone number provided on the complaint, he called me back. I performed a complete site inspection of the Hill 33-22 and the Centerfire 42-22. I reviewed location records, which did not show any abnormal operating conditions at the time of the complaint. I also performed a 24 hour sound study from the complainants residence on 12-11-2020. Also on 12-11-2020 I performed inspections on ROW near the location noted in complaint and the complainants residence.

No violation of COGCC rules where observed at the time of the inspections of the locations listed by the complainant nor within Whispering Pines ROW.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Facility ID: 276196 Type: WELL API Number: 071-08316 Status: PR Insp. Status: PR

Complaint

Comment:

Field Inspector Assigned: Tom E. Beardslee

Complaint Received:

Date: 12/3/2020

Complaint Contacted:

Date: 12/3/2020 Time 11:30 Hrs

Location #: 260968 & 287124

Inspection Document #: 695103720, 695103721

Nature of complaint: Noise/road conditions.

Field Inspector Actions:

On 12-03-2020, I was contacted by my supervisor Steve Labowskie in reference to a complaint received by the COGCC in reference to noise and road conditions. The complaint states that Noise from the Hill 33-22 Well, the Centerfire 42-22 well the Cottontail Compressor station is very loud, at times they can be heard inside of complainants cabin. Noise typically occurs Mornings and night. Sometimes all day, wind dependent with complainant's location; at the sites, the noise is continuous all day. Noise was described as noise you hear and feel. The complaint also states that the roads within Whispering Pines Estates, un named, 43.5, 30.1. The Roads are not kept up to the standards of the Road Use Agreement that was put in place upon the start of the gas wells and road construction.

On 12-03-2020 at 11:30, I attempted to make contact with the complaint on his home phone number provided on the complaint, he called me back. I performed a complete site inspection of the Hill 33-22 and the Centerfire 42-22. I reviewed location records, which did not show any abnormal operating conditions at the time of the complaint. I also performed a 24 hour sound study from the complainants residence on 12-11-2020. Also on 12-11-2020 I performed inspections on ROW near the location noted in complaint and the complainants residence.

No violation of COGCC rules where observed at the time of the inspections of the locations listed by the complainant nor within Whispering Pines ROW.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Berms	Pass	Check Dams	Pass			
Drains	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695103723	24 hour sound study	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5323820