

Inspection Photos

API: 071-07778

Operator: OGRIS OPERATING LLC

Inspection Date: 1/6/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 1/6/2021

Inspection Photos



Photo 1. Facing northwest along the main access road. The culvert along the access road has been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 1/7/2021

Inspection Photos



Photo 2. Facing southwest along the access road ascending the hillside. The road has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 1/7/2021

Inspection Photos



Photo 3. Facing south along the access road ascending the hillside. The culvert along the access road has been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 1/7/2021

Inspection Photos



Photo 4. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 1/7/2021