

Inspection Photos

API: 071-09173

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/6/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021

Inspection Photos



Photo 1. Facing east. Erosion along the access road has been repaired and culverts maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021

Inspection Photos



Photo 2. Facing east. Erosion along the access road has been repaired and culverts maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021

Inspection Photos



Photo 3. The erosion along the fill slope of the road has been repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021

Inspection Photos



Photo 4. Facing south along the access road. Drainage is directed toward the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021

Inspection Photos



Photo 5. Facing south toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09173 | Date: 1/6/2021