

Inspection Photos
Location Name: Jacks Draw Unit 20
Location ID: 416378



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Jacks Draw Unit 20
Location ID: 416378



Photo 2. No bradenhead access apparent.



Photo 3. No bradenhead access apparent.