

Inspection Photos
Location Name: Pad 6
Location ID: 333026



Photo 1: Wellhead; No sign, disconnected automation



Photo 2: Wellhead; No sign, disconnected automation

Inspection Photos
Location Name: Pad 6
Location ID: 333026



Photo 3: Wellhead; No Sign, disconnected automation



Photo 4: Location of PA wellheads

Inspection Photos
Location Name: Pad 6
Location ID: 333026



Colorado Oil & Gas Conservation Commission
40.45483, -104.87375, 1431.6m, 216°
Jan 6, 2021 10:28:17 AM

Photo 5: Equipment removed