



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Locadtion.

Fork Unit 11-18-1-1

API: 05-103-08288

Inspection: 700404887



39.95917, -108.77839, 5763.7ft, 26°
01/07/2021 02:20:39 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pit, meter building, separator.

Fork Unit 11-18-1-1

API: 05-103-08288

Inspection: 700404887