



39.94989, -108.7778, 5704.4ft, 39°
01/07/2021 03:15:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Photo 1. Pump jack.

Fork Unit 6-19-1-1W

API: 05-103-08440

Inspection: 700404889







39.94945, -108.7751, 5602.8ft, 42°
01/07/2021 03:23:09 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Fork Unit 6-19-1-1W

API: 05-103-08440

Inspection: 700404889