

Inspection Photos
Operator: Epic Energy
API: 067-05404
Date: 1/6/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern edge facing northward. Revegetation is progressing with shrubs and grasses such as rubber rabbitbrush, western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of Russian knapweeds within the eastern project area. Approximately 300 dormant individuals observed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.