

Inspection Photos
Operator: Simcoe
API: 067-07877
Date: 1/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with shrubs and grasses such as rubber rabbitbrush, western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of Russian knapweeds within the eastern and southern project area. Approximately 1000 dormant individuals observed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.