

Inspection Photos

Loc#335405

Operator: Caerus

Insp#: 692401686

Insp Date: 12/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

December 29, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus GMU Location#335405



Photo#2:
Pad area.



Photo#3:
View of Cut Slope.

December 29, 2020