

# *Inspection Photos*

*Loc#334911*

*Operator: Caerus*

*Insp#: 692402839*

*Insp Date: 12/30/20*





Photo#1:  
Overview of Location to Southwest.

December 30, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMU Loc#334911



Photo#2:  
Interim area; unmarked Anchor removed.

December 30, 2020