

# *Inspection Photos*

*Loc#334940*

*Operator: Caerus*

*Insp#: 692402840*

*Insp Date: 12/30/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South.

December 30, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus HMU Loc#334940



Photo#2:  
Area Cheat grass treated.

December 30, 2020



Photo#3:  
Conduit Risers removed.

Caerus HMU Loc#334940





Photo#4:  
Tunneling point on East edge of Pad.

December 30, 2020



Photo#5:  
Looking back at site from tunneling point.