

Inspection Photos

Loc#334942

Operator: Caerus

Insp#: 692402841

Insp Date: 12/30/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South.

December 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Craig Loc#334942



Photo#2:
Area stormwater repaired.

December 30, 2020



Photo#3:
Suspected subsidence.

Caerus Craig Loc#334942



Photo#4:
Equipment parked on South end of site.

December 30, 2020



Photo#5:
Equipment parked on South end of site.

Caerus Craig Loc#334942