

Inspection Photos

API: 071-08264

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021

Inspection Photos



Photo 1. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021

Inspection Photos



Photo 2. There is a waster leak coming from the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021

Inspection Photos



Photo 3. Facing north at east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021

Inspection Photos



Photo 4. Facing southeast at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021

Inspection Photos



Photo 5. Facing northeast toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08264 | Date: 1/8/2021