

Inspection Photos  
Location Name: Anschutz-Williams 5-61-27 SWSW  
Location ID: 452726



Colorado Oil and Gas Conservation Commission  
40.36665, -104.20348, 4524.3ft, 255°  
12/30/2020 14:09:30



Colorado Oil and Gas Conservation Commission  
40.36561, -104.20387, 4563.4ft, 213°  
12/30/2020 14:20:00

Photo 1 – Wellheads

Photo 2 – Tank Battery Signs



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW

Location ID: 452726



**Photo 3 – Tanks Battery**



**Photo 4 – Separators and VRT**



**Inspection Photos**  
**Location Name: Anschutz-Williams 5-61-27 SWSW**  
**Location ID: 452726**



**Photo 5 – Unmarked Risers at Soundwall**



**Photo 6 – Unmarked Riser at Soundwall**

**Inspection Photos**  
**Location Name: Anschutz-Williams 5-61-27 SWSW**  
**Location ID: 452726**



**Photo 7 – Unmarked Risers at Soundwall**



**Photo 8 – Unmarked Riser at Soundwall**



## Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW

Location ID: 452726



**Photo 9 – Risers at VRUs have been marked**